



Please see attached table for coordinates and bearings

Marotere Islands
Lady Alice I
Coppermine I
Whatupuke I
West Chicken I (Mauitaha Island)

Hen and Chickens Islands

Taranga Island
335
Wahine Bay

Sail Rock

Bream Tail
McGregor Rock

Point	Coordinates (DMS)	Coordinates (Decimal)
A	35° 50'12"S, 174° 25'19"E	-35.83667, 174.42194
B	35° 48'48"S, 174° 27'06"E	-35.81333, 174.45167
C	35° 49'05.45941"S, 174° 27'48.67201"E	-35.81818, 174.46352
D	35° 49'41.45938"S, 174° 28'42.67256"E	-35.82818, 174.47852
E	35° 49'49"S, 174° 29'59"E	-35.83028, 174.49972
F	35° 49'59"S, 174° 30'20"E	-35.83306, 174.50556
G	35° 56'29.46202"S, 174° 30'30.67438"E	-35.94152, 174.50852
H	36° 02'41.64"S, 174° 34'17.76"E	-36.0449, 174.5716

Patuharakeke te iwi Trust Board PCR boundaries – compass bearings

From A to B – 133° 56'57" distance of 3.732km.

From B to C – 63° 19'14" distance of 1.199km.

From C to D – 50° 41'49" distance of 1.752km.

From D to E – 83° 3'53" distance of 1.930km.

From E to F – 59° 41'28" distance of 0.611km.

From F to G - 1° 16'20" distance of 12.038km.

From G to H – 26° 22'30" distance of 12.804km.